

Environmental Performance Report

Project Details

Project Name: [Barangaroo Cutaway Cultural Facility](#)

Project Number: [200290](#)

Project Location: [1 Merriman St, Barangaroo NSW 2000](#)

Client: [Infrastructure NSW](#)

Name of principal contractor: [FDC Construction \(NSW\) Pty Limited](#)

Company address: [22-24 Junction St, Forest Lodge NSW 2037](#)

ABN: [72 608 609 427](#)

Environmental Tasks Checklist

JUNE 2024

Status: Closed (Task ID:243699)

Type	Location
Environmental	
Category	Additional Info
Compliance	Trades putting general waste in rubble bin
Due Date	User Assigned To
19/06/2024 23:59:00	Lucas Aragona (FDC CONSTRUCTION (NSW))
Completed Date	Owner
19/06/2024 17:30:08	Lucas Aragona (FDC CONSTRUCTION (NSW))
Closed Date	Issue Date
19/06/2024 17:30:08	19/06/2024 17:12:43

JULY 2024

Status: Closed (Task ID:246852)

Type	Location
Environmental	
Category	Additional Info
General	Water Bubbler to be wiped off every day
Due Date	User Assigned To
21/07/2024 23:59:00	Albert Bayona (CBD Property Services NSW PTY LTD)
Completed Date	Owner
18/07/2024 11:11:42	Fernando Arrua (FDC CONSTRUCTION (NSW))
Closed Date	Issue Date
18/07/2024 12:22:14	18/07/2024 06:18:07

Status: Closed (Task ID:247006)

Type	Location
Environmental	
Category	Additional Info
General	Recycling bins are required in the lunchroom.
Due Date	User Assigned To
21/07/2024 23:59:00	Primary Contacts (FDC CONSTRUCTION (NSW))
Completed Date	Owner
18/07/2024 08:59:00	Fernando Arrua (FDC CONSTRUCTION (NSW))
Closed Date	Issue Date
18/07/2024 08:59:00	18/07/2024 06:18:07

Status: Closed (Task ID:247623)

Type	Environmental	Location	
Category	General	Additional Info	Workers drilling into concrete slab, p2 Mask is required.
Due Date	26/07/2024 23:59:00	User Assigned To	Primary Contacts (GS Building)
Completed Date	30/07/2024 06:36:50	Owner	Fernando Arrua (FDC CONSTRUCTION (NSW))
Closed Date	30/07/2024 06:36:50	Issue Date	25/07/2024 11:34:41

Status: Closed (Task ID:247859)

Type	Environmental	Location	
Category	Compliance	Additional Info	Geotech protection is required.
Due Date	28/07/2024 23:59:00	User Assigned To	Primary Contacts (Axis Plumbing (Small Works) Group Pty Ltd)
Completed Date	31/07/2024 11:02:15	Owner	Fernando Arrua (FDC CONSTRUCTION (NSW))
Closed Date	31/07/2024 11:02:15	Issue Date	25/07/2024 11:34:41

AUGUST 2024

Status: Closed (Task ID:250252)

Type	Environmental	Location	
Category	General	Additional Info	Geotech fabric to be fixed on drainage
Due Date	17/08/2024 23:59:00	User Assigned To	Primary Contacts (FDC CONSTRUCTION (NSW))
Completed Date	15/08/2024 09:03:04	Owner	Marc Anthony (FDC CONSTRUCTION (NSW))
Closed Date	15/08/2024 09:03:04	Issue Date	14/08/2024 12:16:20

SEPTEMBER 2024

Status: Closed (Task ID:255719)

Type Environmental	Location
Category General	Additional Info Clean up site emergency equipment (nurse calls and fire alarms)
Due Date 19/09/2024 23:59:00	User Assigned To Jorge Oancea (FDC CONSTRUCTION (NSW))
Completed Date 19/09/2024 07:53:35	Owner Jorge Oancea (FDC CONSTRUCTION (NSW))
Closed Date 19/09/2024 07:53:35	Issue Date 18/09/2024 15:37:59

OCTOBER 2024

Status: Closed (Task ID:260628)

Type Environmental	Location
Category General	Additional Info FDC & CBD-Footprints from B1&B2 to be cleaned. Install sticky mats on B1 & B2
Due Date 16/10/2024 23:59:00	User Assigned To Primary Contacts (FDC CONSTRUCTION (NSW))
Completed Date 16/10/2024 18:16:51	Owner Jorge Oancea (FDC CONSTRUCTION (NSW))
Closed Date 16/10/2024 18:16:51	Issue Date 16/10/2024 17:31:52

NOVEMBER 2024

Status: Closed (Task ID:265559)

Type Environmental	Location
Category General	Additional Info Foot Prints in lift and outside main entrance
Due Date 17/11/2024 23:59:00	User Assigned To Primary Contacts (FDC CONSTRUCTION (NSW))
Completed Date 15/11/2024 06:29:39	Owner Fernando Arrua (FDC CONSTRUCTION (NSW))
Closed Date 15/11/2024 06:29:39	Issue Date 14/11/2024 18:39:48

Status: Closed (Task ID:266999)

Type	Environmental	Location	
Category	General	Additional Info	New water bubblers new to be cleaned and connected to power
Due Date	25/11/2024 23:59:00	User Assigned To	Primary Contacts (FDC CONSTRUCTION (NSW))
Completed Date	23/11/2024 12:53:22	Owner	Jorge Oancea (FDC CONSTRUCTION (NSW))
Closed Date	23/11/2024 12:53:22	Issue Date	22/11/2024 13:14:03

DECEMBER 2024

Status: Closed (Task ID:271106)

Type	Environmental	Location	
Category	General	Additional Info	Sweep / general housekeeping is required - level 1 / 2
Due Date	15/12/2024 23:59:00	User Assigned To	Primary Contacts (FDC CONSTRUCTION (NSW))
Completed Date	12/12/2024 12:17:15	Owner	Fernando Arrua (FDC CONSTRUCTION (NSW))
Closed Date	12/12/2024 12:17:15	Issue Date	12/12/2024 10:21:07

JANUARY 2025

Status: Closed (Task ID:272641)

Type	Environmental	Location	
Category	General	Additional Info	Wash out bays signage needed
Due Date	13/01/2025 23:59:00	User Assigned To	Primary Contacts (FDC CONSTRUCTION (NSW))
Completed Date	13/01/2025 13:24:22	Owner	Marc Anthony (FDC CONSTRUCTION (NSW))
Closed Date	13/01/2025 13:24:22	Issue Date	10/01/2025 16:52:59

